

300x300 HERKULES X-CNC

Technical data



- It is a highly efficient automatic hydraulically controlled band-saw with multiple material feed.
- The saw has extreme robust construction, in connection with powerful blade of 34 mm width the machine ensures maximal performance.
- The machine is designed for vertical cuts.
- The machine is designed to saw steel materials, but also non-ferrous and light metals. However, we recommend consulting the manufacturer about this option.
- **No other materials may be sawn without approval from the manufacturer.**

Control system:

- Machine is equipped with programmable PLC SIEMENS SIMATIC S7-1200. Drive of band blade, movement of arm and movement of feeder are completely controlled and drive by SIEMENS technology.
- The coloured touch screen HMI SIEMENS TP 700 COMFORT enables easy communication with an operator. It shows working conditions (blade speed, moving to the cut, cutting parameters etc.)
- The machine enables to work with two modes:
 - SEMIAUTOMATIC CYCLE: The machine cuts the material immediately in a semiautomatic mode. The operator uses the feeder of the machine for the manipulation with the material and for the exact feed of the material into the cutting zone. The movement of the feeder is realized by manual buttons or by GTO function. After starting GTO function the operator sets the position of the feeder, presses START GTO button and feeder goes to the set position.
 - AUTOMATIC CYCLE: the feeder feeds the material according to the set program. The operator sets the cutting program, machine realizes these programs, it is possible to make thousand different programs. The part of one program is a complete setting of the cut: blade speed, feed speed, setting of an automatic regulation, setting of the height of the bar to be cut, setting of the length of the bar, angles values and number of pieces. The length and number of pieces it is possible to set in 20 lines, the machine feeds differently set lengths automatically.
- Regulation of cutting feed is realized by controlled system by the servo-motor and throttle valve of hydraulic. Then is reached very precise cutting feed. Operator will input into program required cutting feed (mm/min) and bandsaw this cutting feed precisely set.
- Two basic regimes of automatic system regulation (ASR): ARP a RZP.
 - RZP = Zone regulation. System enable to cut material in 5 zones, because of setting optional cutting feed and blade speed according on blade position.
 - ARP = System of the automatic regulation of the cutting feed rate depending on the cutting resistance of the material or blunting the blade. System offers two basic modes of ARP: BIMETAL and CARBIDE.
 - BIMETAL mode is suitable for optimization of the cutting feed when cutting profiles by bimetal blades. The cutting feed is higher if the blade cuts sides of the profile. As the blade reaches the full material, the system reduces the cutting feed automatically so that teeth gap of the blade would not be filled.
 - CARBIDE mode is suitable for cutting of full bars. If the blade is old (blunt), loaded is the cutting feed reduced Reaction time is slower than in mode BIMETAL.
- KKR= check of cut perpendicularity.. Directional system measure vertical position of band blade. If cutting feed is too fast, then bandsaw automatically reduced feed and wait until band blade get into optional position. When blade go back into optional position then system automatically increase cutting feed.
- The control panel is placed in the tightening pulley cover. The control panel is equipped with mechanical buttons and digital display of the machine control system. Mechanical buttons controls basic saw movements (arm, vice, feeder) and cutting cycle start. The safety button is present on the panel aswell. Buttons for controlling the movements of the machine are part of a high-quality foil keyboard.
- Safety module with autodiagnosics.

Construction:

- The machine is constructionally designed in that way, so that it corresponds to extreme exertions in productive conditions. Massive construction enables using of carbide blades comfortably.
- The arm of machine with columns situated as near the clamping vice as possible minimizes vibrations and enables max. cutting performance.

300x300 HERKULES X-CNC

Technical data



- The arm of the machine is robust, heavy weldment and it is designed so that a toughness and a precision of cut was ensured.
- The arm moves along two columns using a four row linear leading with a high loading capacity. Arm movement using hydraulic cylinder.
- Drive pulley and tighten pulley are both metal castings.
- Upper position automatically using: a) Pegas DPP system (touching lath placed closely below tooth of blade: T-bar, linear leading, microswitch, adjusting screw), b) using of incremental sensor for measuring of a position above material. Upper working position of the arm is possible to set in control system.
- Down working position is set with adjustable mechanical stop and microswitch. Down working position of the arm is also possible to set in the saw control system. After reaching bottom working position the arm stops in the position set in the system.
- Main vice with divided jaw that clamps the material in front of as well as behind the cut. The jaws allow a safe grip. The optimization of the chip movement through the fixed jaw directly to the chip extractor.
- Jaws of the main vice move in steel leading using hydraulic cylinder. One jaw is longstroke (the movement by longstroke hydraulic cylinder), one is fixed.
- Regulation valves for setting a vice pressure in hydraulic system.
- Very massive feeder with the feeding step 500 mm moves using hydraulic cylinder and two sharpened bars and teflon cases.
- Incrementally straight sensor for indication of the position of the feeder. The position of feeder is displayed on the control system display. Feeder can have multiple feeding possibility.
- GTO function includes functions ABS, REL a ATB.
- Indication of material in the feeder: optic sensor - it notices that there is a material in the feeder. If there is no material in the feeder, the signal reflects on the glass that is situated on movable jaw and it goes back to the sensor. The machine stops feeding and waits for another bar.
- There is a roller conveyer which supports material in whole feeded length.
- The feeder clamping vice is a robust steel weldment. Jaws ensure safe clamping of the material.
- Jaws of the feeding vice move in steel leading using hydraulic cylinder. One jaw is longstroke (the movement by longstroke hydraulic cylinder), one is fixed.
- Cutting zone is opened from side of the feeder device automatically, extends the blade lifetime when arm is moving to top position.
- The blade leading in guides with hardmetal plates and leading bearings and along cast iron pulleys.
- There is a guide situated on the firm beam on the drive side. On the tightening side there is the guide situated on the moving beam.
- The guide beams of the blade are adjustable in the whole working range. A guide moving is connected with a vice-jaw movement so that to achieve the minimum distance of the guide and material. That is why it is not necessary to set the position manually.
- The guide beam of the blade is placed in wide linear rails with high bearing capacity.
- The saw-band is equipped with a guard, which protects the operator from millings and cutting emulsion.
- Hydraulic tightening of band.
- Automatic indication of blade tension.
- A cleaning brush is driven by hydromotor and ensures perfect cleaning of a blade.
- Drive of machine is solved by worm gear box with maintenanceless oil filling. Three-phases electromotor with double winding, with a frequency converter for a fluent regulation of the blade speed from 20 to 100 m/min. Sturdy flange with shaft. Termoprotection of engine.
- The cooling system for emulsion, led to the guides of the blade and by LoLine system directly to the cut groove.
- Massive base with a tank for chips and with chip extractors. Base is designed for manipulation manipulation with machine by pallet truck and also by any high lift truck.
- Indication of blade tightening and opening of the cover.
- Controlling 24 V.
- Machine is equipped with hydraulic system which controls all functions of that machine. It pushes the arm to cut, pulls up the arm, opens and closes vices, moving of feeder.

300x300 HERKULES X-CNC






Technical data



Basic equipment of the machine:

- Slide of cut pieces.
- Chip extractor
- Lighting of workink space.
- Band saw blade.
- Set of spanners for common service.
- Manual instructions in eletronic form (CD).

utting parameters:

		 0°
	D [mm]	300
	a x b [mm]	300 x 300
	a x b [mm]	300 x 220

° Cutting bundles without vertical clamp. HP = accessory at extra cost. When HP is used, the cutting parameters will be limited.

Cutting parameters

The shortest cutting	mm	10
The smallest divisible diameter	mm	30
The shortest rest durring one cut	mm	50
The shortest rest durring one cut (with HP)	mm	65
The shortest rest in automatic cycle	mm	120
The shortest rest in automatic cycle(with HP)	mm	135
One feed step of the material Min	mm	5
One feed step of the material max	mm	505
Multiple feed	mm	19 999

* possibility to order special bars to clamp smaller diameter – accessory

Performance parameters

drive of the blade	kW	3,0
drive of the hydraulic aggregate	kW	0,75
pump of the cooling emulsion	kW	0,09
Chip transporter	kW	0,12
Cooling Mi	kW	0,06
Control circuit	kW	0,5
total input	kW	5,8
cutting speed – fluently set	m/min	20-100
diameter of the blade	mm	4520x34x1,1
electric connection	kW	3x400V, 50 Hz, TN-S

Working movements

Cutting feed	Hydraulically
Material feed	Hydraulically
Clamping of material	Hydraulically
Blade tension	Hydraulically
Cleaning of the blade	A cleaning brush is actively driven by the hydromotor

300x300 HERKULES X-CNC

Technical data



Parameters						
length		width		Height		weight
[Lmin]	[Lmax]	[Bmin]	[Bmax]	[Hmax]	[V]	(kg)
2230	2510	1450	2280	2050	800	1420

A technical drawing of the 300x300 HERKULES X-CNC saw machine. The drawing shows the machine from a side perspective. Dimension lines indicate the following measurements: Lmax (total length), B (width), H (height), and V (height of the chip extractor). The machine is shown in a grey color.

Lmin = the saw without the chip extractor

Bmin = the saw without the hydraulic cylinder of the feeder